## PORTABLE APPLIANCE TEST CERTIFICATE

Customer		Designaband								
Site Address		em	ail info@designaba	nd.com						
H/O Address		129 Maryland road London N22 5AS								
Contact		Da	wid Brooks 020 888	9 0553						
Manufacturer	Kewtech	Model	KT71	Serial	7000565	Date Calibra				

DATE OF TEST	26/06/2014
NEXT TEST DATE	25/06/2015
ENGINEER	GW
AUTHORISATION No.	ZMN 251-1

28/8/2013

ID No.	Label No.	Description	Location	Manufacturer	Serial No	Class 1-1 2-2 3-IT	Visual Pass /Fail	Fuse (Amps)	20A / 200ma	Bond	Insul ation	Leak		Comments	PASS	FAIL
_	11765	Amplifier		Mesa		3	Pass		200ma		N/A	P/F	Pass		Pass	
0002	11766	pedal power		voodoo lab		3	Pass		200ma	Pass	N/A	P/F	Pass		Pass	
0003	11767	lead				1	Pass	13	20A	Pass	P/F Pass	N/A			Pass	
	11768	power sply				2	Pass		N/A		P/F Pass	N/A		visual only	Pass	
-	11770	power sply				2	Pass		N/A		P/F Pass	N/A		visual only	Pass	
0006	11771	power sply		apple		3	Pass		200ma		N/A	P/F		visual only	Pass	
0007	11772	8 way		surgguard		3	Pass	13	200ma	Pass	N/A	P/F	Pass		Pass	
8000	11773	power sply				2	Pass	4	N/A		P/F pass	N/A			Pass	
0009	11774	lead for above				2	Pass	5	N/A		P/F pass	N/A			pass	-
0010	11775	lead				1	Pass	13	20A	Pass	P/F pass	N/A			Pass	
0011	11776	lead				1	Pass	13	20A	Pass	P/F pass	N/A			Pass	
0012	11777	power sply		roland		2	Pass		N/A		P/F pass	N/A			Pass	
0013	11778	lead				2	Pass	5	N/A		P/F pass	N/A			Pass	
0014	11779	power sply		behringer		2	Pass		N/A		P/F pass	N/A			Pass	
0015	11780	ext lead				1	Pass	13	20A	Pass	P/F pass	N/A			Pass	
0016	11781	lead				1	Pass	13	20A	Pass	P/F pass	N/A			Pass	
0017	11782	pedal power				1	Pass		20A	Pass	P/F pass	N/A			Pass	
0018	11783	power sply				2	Pass		N/A		P/F pass	N/A			Pass	
0019	11784	adapt			7	1	Pass		20A		P/F	N/A		visual only	Pass	
0020	11785	power sply		power bank		3	Pass		200ma	Pass	N/A	P/F	Pass		Pass	
0021	11786	power sply		power bank		3	Pass		200ma	Pass	N/A	P/F	Pass		Pass	
0022	11787	lead				1	Pass	13	20A	Pass	P/F Pass	N/A			Pass	
0023	11788	amplifier		aquilar		3	Pass		200ma	Pass	N/A	P/F	Pass		Pass	
0024	11789	Amplifier		boogie		3	Pass		200ma	Pass	N/A	P/F	Pass		Pass	
0025	11790	lead				1	Pass	13	20A	Pass	P/F pass	N/A			Pass	
0026	11791	amplifier				3	Pass		200ma	Pass	N/A	P/F	Pass		Pass	
0027	END	End							0		P/F	N/A				
0028									0		P/F	N/A				
0029									0		P/F	N/A				
0030									0		P/F	N/A				