Electrical Appliance Maintenance Register

for

Band Equipment 23-25 Aintree Rd Keytec 7 Business Pk Pershore

Customer Ref. No.:

43302



Inspection Date:

October 2066

IsoLec Ltd, Larksmead, 19 Maple Avenue, Perhore, Worcs, WR10 1NL Tel: 01386 860094

Index:

Strategy

ISO9001 Audit





Appliance Register

Fail Certificates



Pass Certificates



General Recommendations











Premises Tested:

Band Equipment 23-25 Aintree Rd Keytec 7 Business Pk Pershore Worcs WR10 2JN

CRN: 43302

In accordance with the guidelines published by the Institute of Electrical Engineers and the Health Safety Executive, the following has been adopted as an ongoing strategy for the maintenance of portable electrical aplliances on this site.

| Type of appliance | Location | Frequency | Test / Inspection |
|-------------------|---------------|-----------|-------------------|
| All Class 1 | All Uses | Annual | Test |
| Class 2 | Low Risk Use | Annual | Inspection |
| Class 2 | High Risk Use | Annual | Test |
| | | | |

Notes:

The above forms the basis of the strategy. It may be varied for specific appliances or locations as dictated by the risk assessment made at the time of testing.

Health and Safety is the responsibility of ALL members of staff, and all users of electrical equipment must be encouraged to carry out User Checks (simple visual inspections) on a regular basis, reporting any signs of damage or disrepair to the Responsible Person.

18 September 2013

for

Band Equipment 23-25 Aintree Rd

Pershore

WR10 2JN

Worcs

Keytec 7 Business Pk

Iso9001 Audit Trail

Premises Tested:

Band Equipment 23-25 Aintree Rd Keytec 7 Business Pk Pershore Worcs WR10 2JN CRN: 43302

Processing

Carried out by S. M. Smith for Isolec Ltd at Larksmead, 19 Maple Ave, Pershore, WR10 1NL using Intel Dual Core Pentium Computer "Steve", with Microsoft Access 2003 on Windows Vista.

Engineer:



Anthony Daysh

Used the following equipment: PAT Type: Megger PAT 4DV Serial No: 031103/5740 I confirm that I have carried out Portable Appliance Testing at the above premises in accordance with the Institute of Electrical Engineers Code of Practice for in-service Inspection and Testing of Electrical Equipment.

Graysh

for

Band Equipment 23-25 Aintree Rd Keytec 7 Business Pk Pershore Worcs WR10 2JN

Appliance Register

Premises Tested:

Band Equipment 23-25 Aintree Rd Keytec 7 Business Pk Pershore Worcs WR10 2JN

CRN: 43302

| <u>Appliance ID</u> | Description | Date Tested |
|---------------------|--------------------|-------------|
|---------------------|--------------------|-------------|

Music Equipment

Band Equipment

23-25 Aintree Rd

Pershore

Worcs WR10 2JN

Keytec 7 Business Pk

| 276902 | EXT CABLE 4 WAY | 060913 |
|--------|-----------------|--------|
| 174877 | ICOLOR LIGHTS | 060913 |
| 176731 | MAINS LEAD | 060913 |
| 211131 | ICOLOR LIGHTS | 060913 |
| 211133 | SHURE MC | 060913 |
| 211135 | SHURE MC | 060913 |
| 213266 | MAINS LEAD | 060913 |
| 213267 | EXT CABLE 2 WAY | 060913 |
| 246963 | EXT CABLE 4 WAY | 060913 |
| 276885 | EXT CABLE 4 WAY | 060913 |
| 276884 | SPEAKERS GTX | 060913 |
| 276883 | EXT CABLE 4 WAY | 060913 |
| 276886 | MINI DISC | 060913 |
| 276887 | SPEAKERS GTX | 060913 |
| 276889 | MAINS LEAD | 060913 |
| 276891 | SPEAKERS GTX | 060913 |
| 276893 | MAINS LEAD | 060913 |
| 276895 | MAINS LEAD | 060913 |
| 276897 | MAINS LEAD | 060913 |
| 276899 | MAINS LEAD | 060913 |
| 276901 | SPEAKERS GTX | 060913 |
| 38210 | MAINS LEAD | 060913 |
| | | |

Total No. of appliances in Music Equipment, 22

Total No. of appliances in Asset Register, 22

for

Fail Certificate

Premises Tested:

Band Equipment 23-25 Aintree Rd Keytec 7 Business Pk Pershore Worcs WR10 2JN

CRN: 43302

Any Appliance detailed below has failed an electrical test / inspection, for the reasons as stated, and must be withdrawn from use until repaired or discarded. Further information, where available, may be obtained from Isolec, together with advise on possible repairs.

None

Band Equipment 23-25 Aintree Rd Keytec 7 Business Pk Pershore Worcs

WR10 2JN

for

Pass Certificate

Premises Tested:

Band Equipment 23-25 Aintree Rd Keytec 7 Business Pk Pershore Worcs WR10 2JN CRN: 43302

The following is a list of the appliances that have been examined, electrically tested where appropriate, and deemed fit for purpose and safe to use. :

| Date | App. ID | Description | Visua P | l olar | Earth itv Ir | sulati | Load on | Touc | Test | Eng. |
|--------|---------|-----------------|------------|-----------|-----------------|--------|------------|------|------|------|
| 060913 | 38210 | MAINS LEAD | Р | S | | ~ | | | V | AD |
| | | | - | | - | - | - | - | | |
| 060913 | 174877 | ICOLOR LIGHTS | Р | S | 0.196 | ^50.0 | - | - | C1N | AD |
| 060913 | 176731 | MAINS LEAD | Р | S | - | - | - | - | V | AD |
| 060913 | 211131 | ICOLOR LIGHTS | Р | S | 0.299 | ^50.0 | 0.000 | 0.00 | C1R | AD |
| 060913 | 211133 | SHURE MC | Р | S | - | ^50.0 | 0.000 | 0.00 | C2R | AD |
| 060913 | 211135 | SHURE MC | Р | S | - | ^50.0 | 0.000 | 0.00 | C2R | AD |
| 060913 | 213266 | MAINS LEAD | Р | S | - | - | - | - | V | AD |
| 060913 | 213267 | EXT CABLE 2 WAY | Р | Р | 0.237 | ^50.0 | - | - | EXT | AD |
| 060913 | 246963 | EXT CABLE 4 WAY | Р | Р | 0.106 | ^50.0 | - | - | EXT | AD |
| 060913 | 276883 | EXT CABLE 4 WAY | Р | S | 0.139 | - | 0.000 | 0.00 | EXS | AD |
| 060913 | 276884 | SPEAKERS GTX | Р | S | 0.147 | ^50.0 | 0.000 | 0.00 | C1R | AD |
| 060913 | 276885 | EXT CABLE 4 WAY | Р | Р | 0.239 | ^50.0 | - | - | EXT | AD |
| 060913 | 276886 | MINI DISC | Р | S | - | ^50.0 | 0.000 | 0.00 | C2R | AD |
| 060913 | 276887 | SPEAKERS GTX | Р | S | 0.136 | ^50.0 | - | - | C1N | AD |
| 060913 | 276889 | MAINS LEAD | Р | S | - | - | - | - | V | AD |
| 060913 | 276891 | SPEAKERS GTX | Р | S | 0.133 | ^50.0 | 0.000 | 0.00 | C1R | AD |
| 060913 | 276893 | MAINS LEAD | Р | S | - | - | - | - | V | AD |
| 060913 | 276895 | MAINS LEAD | Р | S | - | - | - | - | V | AD |
| 060913 | 276897 | MAINS LEAD | Р | S | - | - | - | - | V | AD |
| 060913 | 276899 | MAINS LEAD | Р | S | - | - | - | - | V | AD |
| 060913 | 276901 | SPEAKERS GTX | Р | S | 0.122 | ^50.0 | 0.000 | 0.00 | C1R | AD |
| 060913 | 276902 | EXT CABLE 4 WAY | Р | Р | 0.268 | ^50.0 | - | - | EXT | AD |

18 September 2013

for

Band Equipment

23-25 Aintree Rd

Pershore

WR10 2JN

Worcs

Keytec 7 Business Pk

Date App. ID Description

Visual Earth Load Test Polarity Insulation Touc Eng.

Isolec Larksmead 19 Maple Avenue Pershore Worcs WR10 1NL The above is certified to be a true and accurate record of the test and inspection carried out on the appliances on this site.

Signed.

Date....18 September 2013

Notes / Recommendations

for

Band Equipment 23-25 Aintree Rd Keytec 7 Business Pk Pershore Worcs WR10 2JN **Premises Tested:**

Band Equipment 23-25 Aintree Rd Keytec 7 Business Pk Pershore Worcs WR10 2JN

CRN: 43302

The following is a list of abnormalities that were discovered whilst testing. Some may relate to appliances which although electrically safe, have other defects that are worthy of reporting. Other data may relate to the fixed wiring - eg loose and broken sockets etc..

None

Discarded Appliances:

| | | Location Description Removed from | | | n Site | |
|----------|--------|-----------------------------------|-------------|------|-----------|--|
| Date | App ID | Location | Description | Tick | Signature | |
| <u>.</u> | | | · | | · · · · | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | L | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

New Appliances:

| Date | App ID | Location | Description | Visual Examination Tick if OK Signature | | |
|------|--------|----------|-------------|--|---|--|
| r | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | ļ | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | - | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Repaired Appliances:

| | App ID Description Repair Tick if OK S | | | nination | |
|------|--|-------------|--------|------------|-----------------|
| Date | App ID | Description | Repair | Tick if OK | Signature |
| | <u>i. 66</u> | | | | l'angliantair a |
| | | | | | |
| | | | | | - |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | - |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | - |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | - |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | 1 | | | |
| | | + | | | |
| | _ | | | | |
| | | + | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | 1 |
| | | | | | |
| | | + | | | |
| | | | | | |